



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 03/03/2014


Reviewed 

Mine Name: Lake Point Quarry	Permit Number: M/49/0076	Mine Status: Inactive
Operator Name: Ames Construction	Inspection Date: 02/27/2014	Permit Fees: 500
Inspector(s): A. Abate	Inspection Time: 10:30 AM	Bond Amount: \$172,905
Attendee(s): C. Ennis, L. Botellio	Weather: Rain	Bond Escalation: 7/27/2015
Inspection Purpose: Routine Site Visit		Prior Inspection:

Conclusions and Recommendations

No recommendations. Please note that the bond is due for escalation on 7/27/2015.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ames took over this permit in 2010. Mining took place up until 2012. The mine has been idle since 2013. The Division had some concerns about the total acreage of the property versus the 29 acres that the site is bonded for. Ames supplied additional information including a county assessor's parcel map which showed the total acreage for the lot. The 29 acres is within that footprint and is accurately reflected in the maps provided in the NOI.			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>
3.	Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Erosion was noted on the main access road. Discussed blading a ditch along the road to better control runoff.			
4.	Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>
None noted. The site looked very clean.			
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Stockpiles were not noted on maps but are discussed in the text.			
9.	Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Topsoil areas were observed and appeared to be in good condition with vegetation growing on them.			
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Peggy Kelsey, Utah County peggy@utahcounty.gov

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/- Inspection Summary/Inspection Forms/Inspection form 3.0.2.pdf



View looking south into the mine pit area.



Berm alongside the road on the northern end of the permit area.



Topsoil pile in the background.



Erosion was noted along the access road.